

1204 Apple Drive
Mechanicsburg, PA 17055

Telephone 717-787-9037
717-697-0941

February 27, 1989

Remington Arms Co., Inc.
14 Hoefler Avenue
Arms Service Division
Ilion, NY 13357

Re: M/700 Remington Rifle-Malfunctioning Safety and
Trigger Mechanism

Dear Sir:

According to your instructions for repair of the enclosed M/700 rifle, serial number B6215100, the following is a description of the problem:

On two occasions, once following the firing of one round, the trigger would not move after chambering a second round. The safe was in the fire position. On a second occasion, after loading the magazine and chamber, the safe mechanism would not move from the fire to the safe position. Upon unloading and working the bolt several times, the safe would move to the safe position, but, when it was moved to the fire position, the firing pin would release (the trigger was not touched and there were no live rounds in the chamber). This happened several times alongwith the safe and trigger becoming immobilized or stuck before it would function normally.

Please analyze the problem and advise regarding repair.

Sincerely,

D. B. Shaw
Duain B. Shaw