

(2)

A few words about this rifle, although it is relatively old, I am the sole owner and have never adjusted anything. The trigger pull etc. is from the factory. This gun has not been fired very much as I use a .257 Rem. Robts. To a great extent. This rifle has shot well and I am disappointed, to say the least, to return it.

Therefore please do your utmost to correct the situation and I prefer the same style trigger mechanism as I have these on other Remington rifles, Models 721 and 722.

Also, please look at the bolt, there appears to be more shaving of the brass and looks like a little wear at the pin close to bolt face, (you will see shiny spots,) this could be normal wear.

Needless to say, if a new trigger assy. is required, a heavy pull would not be satisfactory for varmint, hunting and target etc.

Please let me know your analysis as early as possible.

Thank you

Robert E. Shriver
1605 Huffman Dr.
Warren, Ohio 44481
Phone 216-834-7775