

April 21, 1992

Mr. Jim Stekl
Remington Arms Company
Products Service
14 Hoefler Avenue
Ilion, NY 13357

RE: 700 ADL 6MM
SN#6347446

Dear Mr. Stekl,

This rifle has been discharging upon bolt closure. The malfunction has not occurred every time the bolt is closed, only sporadically and typically after a failure to cock. Also, the bolt will occasionally fall out of the action.


I do hope the problem can be corrected easily, as this rifle is my favorite groundhog exterminator.

Upon correction, please return the rifle to:

Skuttle Mfg. Co.
Route 10
Marietta, Ohio 45750
Attn: Marty Hansell
Tel: 800/848-9786

Thank you so much for taking care of this for me. If there are any charges, please let me know.

Sincerely yours,


Marty Hansell