

Gear Lift .0075

Trig Bull 4.5 lbs

Gear engagement has been re-set
and re-baled outside of factory

Shaft is missing from overture
screw and Trig adjusting screw.

There is no overture present in
Trig.