

RECEIVING AND ESTIMATING REPORT						COMMENTS		ORDER	
INITIAL JJM		CUSTOMER ORDER NO.		SAFTEY LEVER BROKEN				R 94-06904	
DATE RECEIVED 02/17/94	DATE OPENED 02/24/94	DATE CODE PX 6-73	SERIAL NUMBER 6649099	NEW SERIAL NUMBER	MODEL AND GRADE 700 243		ADL		
ACCESSORIES W/STUDS									
FROM:					SHIP TO:				
SMITH, WALTER 3209 LUANN DR ANTIOCH TN 37013					SMITH, WALTER 3209 LUANN DR ANTIOCH TN 37013				
CUST NO: 092922 C.O.D.									
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		WRITE ☐		PROM. DATE		ESTIMATED	
								VIA UPS	
GUN CONDITION						REPAIR CHARGE \$5.00			
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED						COP UPS			
						EXCISE			
						TAX			
						INSURANCE			
						UPS			
						PARCEL POST			
						TOTAL			
CUSTOMER CONCERN		AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT		
CYCLE		A1	B1						
TRIGGER GROUP			B2			E1	F1		
BOLT ASSY.			B3			E2	F2		
BARREL ASSY.			B4			E3	F3		
REC. ASSY.			B5		D2	E4	F4		
WOOD				C1	D3	E5	F5		
METAL				C2					
MAIN FAULT: Upon receipt, safety assembly would not move from the pin to on/off position. Examination reveals that the engagement pins have been set, and the bottom edges of the rear safety lever have been ground. Action was triggered assembly housed with heavy grinding.									
PARTS				COMMENTS					
				Replace complete trigger assembly & clean action at 1/2 normal replacement cost.					
				Go ahead called customer - he paid for work done.					
REPAIRMAN		PROOF	CLEAN	TEST	TARGET	PATTERN			
GALLERY TESTER		DATE	DATE	DATE	DATE	DATE			
OFFICE COPY									

RD6925 REV. 1/94