

*Received letter
5/29/85 -
Responded to letter
5/29/85*

Justified
February 28, 1985

Walt Smith
3541 Leathertop
Plano, Texas 75075

ILION

RECEIVED
MAY 20 1985
K. D. GREEN

Remington Arms Co.
Department CB
939 Barnum Avenue
Bridgeport, Connecticut 06602

Attention Service Department:

I would like your help with a problem I experienced recently with my Remington Model 600, 6mm rifle. During a recent hunting trip, when jarred slightly, the rifle discharged while the safety was in the "on" position. Fortunately, there were no injuries, although the bullet went through the trunk of my car.

The gun was purchased new in 1976 or 1977 (I can furnish the purchase record, if needed). I have not had this problem or any other related to trigger release since purchasing the rifle. The trigger has not been adjusted or worked while I've owned the gun.

Please advise me of what can be done to prevent the problem in the future.

Sincerely,

Walt Smith
Walt Smith

SERIAL # A6430018