

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: Good R #: 026555
OUTSIDE WORK: SCOPE MOUNTED DATE: 12-18-72
FROM: SO. WIS. SPT. CENT.
FIRED AMMO TYPE: - BELOIT, WIS.
& CONDITION: _____ GUN #: 6580387
ASSEMBLER 73 CODE: OW = 7/72
PROOF: R.E.P.-B INSP.: 73 TEST: 97 GA./CAL.: 3006
HEADING: O.K. CHECKED BY: C. PROSSER
BREECH OPENING: - APPROVED: _____
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

HEAVY LUBRICANT AROUND SEAR, BURR AT REAR OF
HOUSING FROM FIRING PIN HEAD.

COMPLAINT: "FIRES SOMETIMES WITH SAFETY ON"

INCIDENT: PROBABLY FOLLOW-DOWN.

COMMENTS: THE HEAVY LUBRICANT COMBINED WITH SEAR-
BIND PROBABLY HELD THE SEAR IN FIRED POSITION
AND CAUSED FOLLOW-DOWN.