

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO. 4244		COMMENTS		R91-12048	
DATE RECEIVED 06/03/91	DATE OPENED 06/06/91	DATE CODE XE 12-84	SERIAL NUMBER B6654605	MODEL AND GRADE 700 30-06	ADL	ORDER R 91-1204	
ACCESSORIES W/STUDS		L/REAR SIGHT					
FROM: SOUTHLAND GUN WORKS, INC. 1134 HARTSVILLE RD. DARLINGTON SC 29532 USA				SHIP TO: SOUTHLAND GUN WORKS, INC. 1134 HARTSVILLE RD. DARLINGTON SC 29532 USA			
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 6-17-91	VIA UPS	

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW☐ SLIGHTLY WORN☐ VERY WORN☐ MISUSED☐ MARRED

CUSTOMER'S REQUEST

Gun fired when Safety was disengaged

MAIN FAULT

Cannot duplicate complaint, however, disassembly of rifle reveals bottom of receiver, trigger assembly, barrel and magazine follower spring were rusty - rifle had been wet at some time and not properly maintained. Trigger pull 5 1/2 pounds; was left "012" Safety "off" for heavier than normal.

PARTS

Based on heavy safety "off" force, replace trigger assembly at no-charge. Cleaning of rifle should be charged.

REPAIRMAN RBA	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/9