

INITIAL FJB	CUSTOMER ORDER NO. 5136	<i>F. J. [Signature]</i>				Product Service	
DATE RECEIVED 03/30/94	DATE OPENED 03/31/94	DATE CODE PI 6-88	SERIAL NUMBER C6260904	NEW SERIAL NUMBER	MODEL AND GRADE 700 270	FS/CAMO	
ACCESSORIES		SLING STRAP	W/STUDS	W/SWIVELS	L/SIGHTS		

FROM:

SOUTHLAND GUN WORKS INC
1134 HARTSVILLE HWY
DARLINGTON SC 29532

SHIP TO:

SOUTHLAND GUN WORKS INC
1134 HARTSVILLE HWY
DARLINGTON SC 29532

CUST NO:006042 ILIONL

ACCOUNT NUMBER <i>063103</i>	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED 5-14-94	VIA UPS
GUN CONDITION ☐ NEW ☐ LIGHTLY WORN ☒ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED			REPAIR CHARGE <i>20.00</i> EXCISE TAX INSURANCE UPS <i>8.00</i> PARCEL POST TOTAL <i>28.00</i>		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1	<i>Rifle fired when safety was pushed on fire</i>			
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Wp 6-88 Could not duplicate customer concern as received. Trigger Assy. was ruptured and some rust on bottom of receiver. Trigger also adjusted outside of the factory. We do not recommend that the trigger be adjusted outside of the factory. All metal parts should be maintained with a light film of light oil. Exchange trigger Assy. at a special price as a gesture of good will.*

PARTS <i>Trigger Assy. Complete</i>	COMMENTS <i>Trigger pull measured 4 1/2 to 7 LBS A-9 Rel'd. Seat left was .014 Sleng in Cab.</i>
REPAIRMAN <i>[Signature]</i>	PROOF
GALLERY TESTER	DATE
CLEAN ☒	TEST ☒
TARGET	PATTERN
DATE	DATE

OFFICE COPY

RD6925 REV. 1/94