

we are sure the problem has been corrected, we would appreciate your help. Do you know of similar cases where 700 ADL's have accidentally fired? Do you know what type of mechanical problem or factory defect could have caused the problem?

Both John and I appreciate your time and look forward to hearing from you.

Sincerely,

*Bob Spain & John P. Scott*

Bob Spain  
3625 S. 1st Street #231  
Austin, Texas 78704

John P. Scott, III  
8713 Primrose Lane  
Austin, Texas 78758

P.S. Factory ammunition was used in both guns in question.