

RECEIVING AND ESTIMATING REPORT							
CUSTOMER ORDER NO. <i>1111</i>				COMMENTS <i>L SIGHT ON REAR RAMP</i>			
DATE RECEIVED <i>04/26/88</i>		DATE OPENED <i>05/05/88</i>		DATE CODE <i>AW 3-72</i>		SERIAL NUMBER <i>4539015</i>	
ACCESSORIES <i>L/WOOD</i>		SCOPE BASE		MODEL AND GRADE <i>700 243</i>		ORDER <i>R 88-12950</i>	
FROM: <i>VICTOR E SPEAR R R # 2 BOX 61 CHURUBUSCO IN 46723</i>				SHIP TO: <i>VICTOR E SPEAR R R # 2 BOX 61 CHURUBUSCO IN 46723</i>			
ACCOUNT NUMBER				FROM DATE		ESTIMATED	
REPAIR CHARGE				TAX ST		TAX CITY	
INSURANCE				UPS		PARCEL POST	
TOTAL				VIA <i>UPS</i>		\$	
GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ QUOTE							
CUSTOMER'S COMPLAINT <i>"almost every time the bolt in let down it fires and also when the safety is released it fires".</i>							
MAIN FAULT <i>Trigger has been grossly misadjusted outside factory - trigger pull is 1 pound, clean engagement so misadjusted, rifle will not work most of the time.</i>							
PARTS <i>Send repair quotation to either re-adjust trigger or replace trigger assembly, whichever is necessary.</i>							
5/19/88 <i>JLS</i>							
FOR COMPUTER REF. ONLY				PROOF			
				(CLEAN) (TEST) (TARGET)			
				REPAIRMAN <i>J.P.S.</i>			