

RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDER NO.		COMMENTS	
L		L SIGHT ON REAR RAMP	
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER
4/16/81	4/15/81	AW 72	4530015
ACCESSORIES		MODEL AND GRADE	
L		700 743	
		ORDER 88-12950	

FROM:	SHIP TO:
	VILLAGE OF ...
	...
	...
	...

ACCOUNT NUMBER	FROM DATE	ESTIMATED	VIA
063103		5-23-81	
REPAIR CHARGE	TAX STATE	INSURANCE	UPS
35.00	5/10/75		3.44
TAX CITY	PARCEL POST	TOTAL	
		40.19	

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☒ QUOTE

CUSTOMER'S COMPLAINT
 "almost every time the butt is let down it fires and also when the safety is released it fires".

MAIN FAULT
 Trigger has been grossly misadjusted outside factory - trigger pull $\approx$ 1 pound, cam engagement is misadjusted, rifle will not cock most of the time.

PARTS 26345
 Trigger Assy B.C. desired repair quotation to either readjust trigger or replace trigger assembly, whichever is necessary.

4 To 6 WKS
 polehead Chamber 5/17/81
 Check Headings etc.

FOR COMPUTER REF. ONLY	PROOF
	(CLEAN) (TEST) (TARGET)
	REPAIRMAN
	ML

OFFICE COPY