


Since we found the trigger assembly to function properly (at room temperature), we can either clean the present assembly or, if it will better restore confidence in the rifle, we will install a new trigger assembly at no-charge as a good-will gesture (either option is subject to a \$10.00 handling plus return shipping charge). We will await the decision and reply.

Thank you for affording us the opportunity to examine the rifle and report our findings.

Sincerely,



J. A. Stekl, Specialist
Product Service

JAS: tpp