

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

March 10, 1989

Sports South, Inc.
P.O. Box 51367, 410 Kay Lane
Shreveport, LA 71135-0000

Dear Sirs:

Our experts have completed their examination of the Model 700 270 caliber rifle, serial number C6214754, that you returned covered by your return number 327, with the reason that the rifle fires when the safety is moved to the off position.

The returned firearm, which was produced in December of 1987, was found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to shipment from our factory.

The general condition of the rifle appeared to be very good and, in going over the individual parts, we found headspace, recoil shoulders all to be normal.

Examination of the rifle and trigger assembly could not duplicate the reported malfunction. However, it was noted that more than normal force was required to move the safety assembly. Trigger pull and sear lift were measured and found to be well within specification. The only manner in which the rifle could be made to fire is with the safety off and the trigger pulled, as designed.

To insure that your customer's faith in the rifle is restored, we will install a new trigger assembly at no-charge, and will return the rifle as soon as possible.