

RECEIVING AND ESTIMATING REPORT

COMMENTS

STEEL

ORDER
R 92-14659INITIAL
JJMCUSTOMER ORDER NO.
K12769

DATE RECEIVED 07/08/92	DATE OPENED 07/17/92	DATE CODE WI 8-88	SERIAL NUMBER C6279986	NEW SERIAL NUMBER	MODEL AND GRADE 700 243	ADL
---------------------------	-------------------------	----------------------	---------------------------	-------------------	----------------------------	-----

ACCESSORIES
W/STUDS

FROM:

SPORTS WORLD
5800 S LEWIS STE 154
ATTN T L DENTON
TULSA

OK 74105

SHIP TO:

SPORTS WORLD
5800 S LEWIS STE 154
ATTN T L DENTON
TULSA

OK
74105

CUST NO: 005259 WILM L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 7/24/92	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	----------------------	------------

GUN CONDITION
☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☒ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.					E2	F2
BARREL ASSY.					E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Trigger assembly is completely jammed up with WD-40.
 I checked trigger parts on spot shooting field for properly.
 I am owner of gun not to use WD-40 on this life!!

PARTS

COMMENTS

Offer new trigger assembly at
 5000.00 cost the rest of good
 work.

REPAIRMAN RJR	PROOF	CLEAN	TEST	TARGET	PATTE
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV.