

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: USED R #: 22448
 OUTSIDE WORK: SCOPE MOUNTED DATE: 11-8-71
 FROM: THE SPORTSMAN
 FIRED AMMO TYPE: - HARLINGEN, TEXAS
 & CONDITION: _____ GUN #: 276664
 PROOF: R.E.P. ASSEMBLER 64 INSP.: 9 TEST: 87 CODE: RP= 5/67, OT 3= 7/70
 HEADING: _____ GR./CAL.: 7MM 0.280
 BREECH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED, OR BROKEN COMPONENTSTRIGGER BINDS ON GUARD. TRIGGER PULL 2 1/2 POUNDS.COMPLAINT: "FIRES WHEN SAFETY IS PUT IN FIRE POSITION"INCIDENT: FOLLOWS DOWN

COMMENTS: WITH THE TRIGGER PULL LIGHT (2 1/2 POUNDS) AND THE
TRIGGER BINDING ON THE GUARD, IT IS POSSIBLE THAT
TRIGGER-CONNECTOR RETRACTION WOULD BE ERRATIC.
THIS COULD CAUSE FOLLOW ON DOWN WHEN THE TRIGGER
IS PULLED WITH THE SAFETY ON.