

RECEIVING AND ESTIMATING REPORT ✓

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS W/MAG BOX	
DATE RECEIVED 06/06/90	DATE OPENED 06/15/90	DATE CODE WI 8-76	SERIAL NUMBER A6346379	MODEL AND GRADE 700 130-06	ORDER R 90-175
ACCESSORIES L/WOOD L/FOLLOWER L/MAG SPRING SCOPE BASE					
FROM: THE SPORTSMAN'S CTR. 28 WAUGH DR. HOUSTON TX 77007			SHIP TO: THE SPORTSMAN'S CTR. 28 WAUGH DR. HOUSTON TX 77007		
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☒ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"One out of three cycles, the magazine (feed) when the safety is pushed off safety, trigger pull is erratic with a 3 to 5 lb. full difference at any position. At times pull is down as little as 1 1/2 lbs. which is unsafe".

MAIN FAULT

As received, the rifle would sometimes fire upon release of safety. Further examination revealed that trigger was improperly adjusted out of factory — trigger adjustment spring pressure was insufficient to properly return trigger and connector consistently under rear — safety came. An epoxy type glue was present on adjusting screw which prohibited proper readjustment of assembly.

PARTS

Per phone call to Jeannine at "The Sportsman's Center" on 10/11/90 — we agreed to replace the trigger assembly at 1/2 normal price as gesture of good-will (based on age of rifle).

Replace trigger assembly at 1/2 normal price of return Co. — do not charge handling charge.

REPAIRMAN BW	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV.