

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 *Cust. Ample*
 GENERAL CONDITION: NEW R #: 013117
 OUTSIDE WORK: SCOPE MOUNTED DATE: 6-19-72
 FIRED AMMO TYPE: - FROM: SPORTSMEN'S DEN
 & CONDITION: ASSEMBLER 65 MT. SHASTA, CAL.
 GUN #: 6249832
 PROOF: R.F.P.-D INSP.: 74 TEST: 87 CODE: PS=6/69, CH.3=4/72
 HEADING: O.K. GA./CAL.: 7MM
 BREECH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010 (MIN.=.020)
BOTH SEAR AND CONNECTOR DAMAGED ON ENGAGEMENT
CORNERS. CONDITION OF FIRING PIN HOLE & FIRING PIN
POINT INDICATE PRIMER PIERCING HAS BEEN EXPERIENCED.

COMPLAINT: WILL NOT FIRE

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER PROBABLY EXPERIENCED A PIERCED
PRIMER WHICH WITH THE .010 ENGAGEMENT, CAUSED THE
SEAR-CONNECTOR DAMAGE RESULTING IN FOLLOW-
DOWN.