

Dear Remington Arms Company:

Enclosed is my model 700 7mm mag. It's been an excellent and reliable gun. Recently on a shooting trip I encountered a ~~serious problem~~ with my gun.

While shooting, I saw a nest. I fired a round, ejected the shell and put another in the chamber, at which point my gun would not cock for the second round. While trying to figure out what was wrong with my rifle, I pushed my safety to the safety position without my gun being cocked. Then, ~~to next~~ levered the bolt and the gun cocked. When I flipped the safety off the firing pin dropped. Had there been a round in the chamber it would have went off. I pulled the action out of the stock, to see if someth obvious was wrong. I found nothing obvious. When I put the ~~gun~~ action back in the stock the gun started working proper. So I thought, I then placed a round in the gun. Knowing it might possible