

RECEIVING AND ESTIMATING REPORT

COMMENTS

Stekl

R 92-01708

AL CUSTOMER ORDER NO.

S

E. RECEIVED
7/10/92DATE OPENED
01/16/92DATE CODE
XB 12-55SERIAL NUMBER
376343

NEW SERIAL NUMBER

MODEL AND GRADE
722 244 REM

BDL

ESSORIES

L/STUDS L/REAR SIGHT

M:

STEVENS, J R
8222 SPRINGTIME
HOUSTON

TX 77075

SHIP TO:

STEVENS, J R
8222 SPRINGTIME
HOUSTON

TX

77075

CUST NO: 056379 C.G.D

QUANTITY NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

1-25-92

VIA

UPS

CONDITION

NEW

LIGHTLY WORN

MORN

VERY WORN

UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

STOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
BLE	A1	B1				
AGER GROUP	Shell	B2	went off when closing bolt			
T ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
ASSY.		B5		D2	E4	F4
OD			C1	D3	E5	F5
TAL			C2			

IF FAULT

Trigger assembly is contaminated with a gunpowder, sticky residue.
Internal trigger parts are not moving freely nor properly.
Ref has not been maintained properly.

TS

COMMENTS

Clean present trigger assembly, if possible. If not possible, offer new replacement trigger assembly at a normal cost as gesture of good-will.

Ⓟ Note - this rifle is 37 years old!!

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

11