

## Speed Message

To Remington Arms Co. Inc.  
Product Service Dept  
■ Att: Mr. Jim Stekl  
■ 14 Hoefler Ave  
■ Ilion, New York 13357

From Ladell Sump  
■ 104 Lindsey  
■ Bay City, Tx 77414

Subject Return of Mohawk 600 Rifle

Date 8-3-89 19

This rifle was sent off by our dealer for the "fix" of this firing  
problem. The mark "V" is on the trigger housing...

I called you in July about another misfire when loading on this  
rifle.. This is since being fixed.....

You requested me to send to you for your inspection....

Yours truly,

Ladell Sump

Signed

Wilson Jones  
MANUFACTURED IN U.S.A.  
Carbonless

88

Remington Arms Co., Inc  
Product Service Dept.  
Att: Jim Stekl  
14 Hoefler Ave.  
Ilion, New York, 13357

(Note inside)