

RECEIVING AND ESTIMATING REPORT

FROM: _____

ORDER R 11474

DATE RECEIVED _____ ESTIMATED _____

DATE OPENED 5-8-85 VIA JPSMODEL AND GRADE 700ADL - 22-250 SERIAL NO. 6422056DATE CODE CU4-71

FROM:

R.M. Tanner
Farmers Service Center
P.O. Box 252
Madison, VA. 22727

REPAIR CHARGE _____

INS. _____

UPS _____

PARCEL POST _____

TOTAL \$ _____

GUN CONDITION: (NEW) (SLIGHTLY WORN) (VERY WORN) (MISUSED) (QUOTE)

CUSTOMER'S COMPLAINT "When you close the bolt, and take safety off. the gun fires, without touching trigger"MAIN FAULT Trigger very loose on pivot pin - retraction not positive. In addition, inside of Assembly has excess dried lubrication.DEMERIT
CODE

PARTS _____

replace trigger assembly
at no-charge.5/8/85JAS.

FOR COMPUTER REFER. ONLY

PROOF _____

(CLEAN) (TEST) (TARGET)