

December
January 13, 1988
Green Bay, Wisconsin

Remington Arms Co. Inc.
Ilion, New York 13357

Dear Sirs;

In January 1979 I purchased from J.C. Penny Co. Green Bay a Remington Model 700 bolt action 30-06 caliber rifle, serial number A 6617404.

For the past 3 years I have had problems with this rifle. They began when the rifle is exposed to cold weather as is always the case in this geographic area.

Problem # 1 When closing the bolt during shell insertion the rifle fires.

Problem # 2 Upon pulling trigger there is a .3 to 6 second delay from firing pin release.

Problem # 3 Saftey mechanism jams or binds.

Needless to say these malfunctions make this a very dangerous rifle. Having had two different gun-smiths completely check this rifle the problems persist. Therefore I seek your expertise to correct these discrepancies. I shall await your reply. Thank you.

Sincerely;



Harold J. Taylor

2843 Brookview Dr
Green Bay, WI 54313