

Remington.



bcc: Arms Service
R-89-03043
Hold for reply
Bill Ericson
Jim Hutton

REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

March 15, 1989

Mr. Ed Taylor
Rte. 3, Box 281-A
Walnut Grove, MO 65770

Dear Mr. Taylor:

Examination has been completed on the two (2) Model 700 BDL rifles; 22/250 Rem. caliber, serial number 260423 and 270 Win. caliber, serial number 363066, that you returned to us because of malfunctions encountered with the 22/250 caliber rifle.

The returned firearms (serial number 260423 was produced in February of 1967; serial number 363066 was produced in August of 1968) were found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating they had successfully passed all necessary tests and inspections prior to being shipped from our factory.

The general conditions of the rifles appeared to be well-used but good and, in going over the individual parts, we found headspace, recoil shoulders and chambers all to be normal.

Examination of the rifles and trigger assemblies could not produce any malfunctions. All tolerances and dimensions were found to be normal, including trigger pulls and sear lifts with the safeties in the on-safe positions. Factory seals were intact on the adjustment screws, indicating that no adjustment had been made to the triggers outside our factory.

Since we found the firearms to be completely correct and to function normally in every respect, we are prepared to return them to you in their present condition. However, if you desire, we will install new trigger assemblies at no-charge, as a gesture of good