

RECEIVING AND ESTIMATING REPORT

DATE RECEIVED		DATE OPENED		DATE CODE		SERIAL NUMBER		MODEL AND GRADE		SHIP TO		ORDER	
10/16/79		10/16/79		10/16/79		1012452		700-74M		SHIP TO		R	
ACCESSORIES													
L/ REAR SIGHT													
FROM: THERNLUND, MARTIN 281 FILBERT AVE ELSMERE DE 19805													
SHIP TO: THERNLUND, MARTIN 281 FILBERT AVE ELSMERE DE 19805													
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		WRITE ☐		CLEAN/TEST		FROM DATE		ESTIMATED		VIA UPS	
REPAIR CHARGE		TAX		INSURANCE		UPS		PARCEL POST		TOTAL			
GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED													
CUSTOMER'S REQUEST													
<i>Sometimes rifle fires when safety is released; sometimes the firing pin will not cock, it simply follows the bolt down.</i>													
MAIN FAULT <i>Trigger assembly stuck from some unknown cause - internal parts not moving freely.</i>													
PARTS <i>Replace trigger assembly at no charge as gesture of good-will.</i>													
REPAIRMAN		PROOF		CLEAN		TEST		TARGET		PATTERN			
GALLERY TESTER		DATE		DATE		DATE		DATE		DATE			

RD6925 REV 6/86