

RECEIVING AND ESTIMATING REPORT

INITIAL FPS		CUSTOMER ORDER NO.		COMMENTS 84	
DATE RECEIVED 12/11/90	DATE OPENED 12/17/90	DATE CODE BD 1-77	SERIAL NUMBER A6408324	MODEL AND GRADE 700 30-06 BDL	ORDER R 90-327
ACCESSORIES W/STUDS					

FROM:

TOM'S HANDLOADING CENTER
45A WINN ST
BURLINGTON MA 01803

SHIP TO:

TOM'S HANDLOADING CENTER
45A WINN ST
BURLINGTON MA
01803

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 1-4-91	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	---------------------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☒ MARRED ^{W/O}

CUSTOMER'S REQUEST inspect and repair - rifle discharged when the safety was put in the "On" position

MAIN FAULT Cannot duplicate complaint, as by design a m/200 rifle cannot fire with the safety "on" since the firing pin is blocked. Sent to J. Stet
Trigger and safety assembly operate properly - trigger pull 4 1/2 pounds; over-
lift .008". No fault found

PARTS		Offer to return rifle as-is or, we can install a new trigger assembly at 1/2 normal cost, as a gesture of good-will if it will better restore confidence in the rifle.				
REPAIRMAN 64	PROOF	CLEAN	TEST	TARGET	PATTERN	
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE	

OFFICE COPY

RD6925 REV. 7/90