

RECEIVING AND ESTIMATING REPORT ✓

INITIAL		CUSTOMER ORDER NO.		COMMENTS			
JLM							
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER	
12/07/91	02/15/91	DX 9-73	6676256	700 30-06 ADL		R 91-0454	
ACCESSORIES		W/STUDS					

FROM:

TOM'S GUN SHOP
203 EAST MADISSON
MEMPHIS

MO 63555

SHIP TO:

TOM'S GUN SHOP
203 EAST MADISSON
MEMPHIS

MO 63555

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION:

☐ NEW☐ SLIGHTLY WORN☐ VERY WORN☐ MISUSED☐ MARRED

CUSTOMER'S REQUEST

"Gun will not fire sometimes & gas off when you close bolt sometimes".

MAIN FAULT

As received, trigger assembly inoperative. Disassembly revealed internal parts of trigger assembly will not move due to contamination by sticky residue. Trigger and connector are sticking to trigger assembly side plates. Rifle has not been properly maintained.

Offer replacement trigger assembly at 1/2 normal cost, as gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90