

## LIMITED DISTRIBUTION

PRODUCT SAFETY SUBCOMMITTEE MEETING  
OCTOBER 30, 1978

PRESENT:

SUBCOMMITTEE

E. F. BARRETT, CHAIRMAN  
R. A. PARTNOY  
E. G. LARSON

OTHER

J. E. PREISER  
H. K. BOYLE  
R. B. SPERLING, ACTING SECRETARY

MCHAWK MODEL 600, ETC.

It was reported that every replacement trigger assembly is being gauged at Ilion and a 10% quality check is being conducted.

Remington Representatives are now in Texas to review recommended gunsmiths' procedures on correcting guns and to see what, if any, problems are being encountered.

R. B. Sperling  
Acting Secretary

RBS:hss

REM 0002593

10N 0008015