

I. YES GUN EXAMINATION REPORT NUMBER: 83 MODEL: 600
 GENERAL CONDITION: USED R #: 07834
 INSIDE WORK: SWIVELS & RECOIL PAD DATE: 3-2-79
ADDED STOCK FINISH REMOVED FROM: - TSCHRIETER
 LOADED AMMO TYPE: NOT KNOWN GEN DELIVERY
 HILL REST ALBERTA CANADA
 GUN #: 6532853
 & CONDITION: _____
 PROOF: 19EP1 1/1 INSP.: J TEST: 76 CODE: AW-3-72
 LOADING: CLOSE TO MAX GA./CAL.: 308
 REECH OPENING: OK CHECKED BY: M HARRY
 COIL SHOULDERS: OK APPROVED: 7/11 3/30/79
 HAMMER: OK APPROVED: 6/8 3/30/79
 EST: _____ APPROVED: R.F.B. 3-30-79
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 7/11 3-30-79
RIFLE SPOTS ON BBL, BOLT HAS COLOR WASH OFF
FRONT SIGHT BROKEN, TRIG GUARD BROKEN
 COMPLAINT: RIFLE FIRED WHEN PUSHING SAFETY OFF
 INCIDENT: LAYED RIFLE ON SEAT TO EJECT LIVE ROUND
RIFLE FIRED, DAMAGING DASH OF TRUCK
AND BUDDY'S GUN.
 COMMENTS: Gun involved in recall program.

Weight of pull and engagement screw appears to
 have been tampered with. No sealant.