

RECEIVING AND ESTIMATING REPORT

INITIALS		CUSTOMER ORDER NO.		COMMENTS	
UJS					
DATE RECEIVED	DATE ORDERED	DATE PAID	SERIAL NUMBER	MODEL AND GRADE	ORDER
12/25/87	12/28/87	12/29/87	255134	7001-22-28-2-200	R
ACCESSORIES		SHIPPING BASE & DELIVERY CHARGES			
FROM			SHIP TO		
VERNON TUCKER 1200 OAK STREET BURNET TX 78611			VERNON TUCKER 1200 OAK STREET BURNET TX 78611		
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	FROM DATE	ESTIMATED	DATE USED
					UPS
REPAIR CHARGE					
TAX					
INSURANCE					
UPS					
PARCEL POST					
TOTAL					
GUN CONDITION:					
☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED					
CUSTOMER'S REQUEST					
1) "This gun discharges when loading or unloading" 2) bolt face shows wear on closing bolt MAIN FAULT 1) no fault found - operates normally trigger pull 4 3/4 #, S&W lift .006" 2) Extractor and rivet <u>not</u> set properly, replace extractor N/C PARTS Replace trigger assembly at N/C, per phone call to customer (same style safety - bolt lock) 2) Lubricate bolt lugs - slight galling. Charge \$10.00 handling plus return shipping REPAIRMAN J.E.S. GALLERY TESTER					
PROOF	CLEAN	TEST	TARGET	PATTERN	
DATE	DATE	DATE	DATE	DATE	DATE

RD5925 REV. 6/88