## **BARBER - Kinzer PPS GAL RE0005174**

Since we found the trigger assembly to be outside our specifications, we can either readjust the present assembly or, if it will better restore confidence in the rifle, we will install a new trigger assembly at no-charge as a goodwill gesture. We will await the decision and reply.

Thank you for affording us the opportunity to examine the rifle and report our findings.

Sincerely,

.W. Sanita, Specialist

Product Service

DJS:tpp

Remington Arms Company, Inc.