

*Customer Complaint*

P.I. NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700 BDL  
GENERAL CONDITION: NEW R #: 15003  
OUTSIDE WORK: TRIGGER PULL REDUCED TO DATE: 7-30-71  
ONE POUND. FROM: UNITED DIST.  
FIRED AMMO TYPE: - GALVESTON, TEXAS  
& CONDITION: \_\_\_\_\_ GUN #: 6408400  
PROOF: R.E.P. INSP.: 74 TEST: 98 CODE: LO: 2/71  
HEADING: O.K. GA./CAL.: 270 WIN.  
BREECH OPENING: - CHECKED BY: C. PROSSER  
RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_  
CHAMBER: O.K. APPROVED: \_\_\_\_\_  
TEST: No APPROVED: \_\_\_\_\_  
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

ADJUSTING SCREW FOR TRIGGER PULL UNSEALED  
AND ADJUSTMENT ALTERED.

COMPLAINT: FIRING PIN ENGAGES & FIRES WHEN BOLT IS  
PUSHED FORWARD.

INCIDENT: FOLLOW DOWN

COMMENTS: WHEN TRIGGER PULL WAS CORRECTED ENGAGE-  
MENT OF SEAR AND TRIGGER CONNECTOR WAS .025-  
MIN. IS .015 WITH TRIGGER PULL REDUCED THE  
'SPRING WILL NOT RETRACT THE TRIGGER CONNECTOR  
CORRECTLY AND FOLLOW DOWN MAY RESULT.