

Cust Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: GOOD R #: 027088
OUTSIDE WORK: NO DATE: 12-18-72
FROM: VALLEY HOME SUPPLY ^{Co.}
FIRED AMMO TYPE: - MILESBERG, PA.
& CONDITION: _____ GUN #: 6261266
PROOF: R.E.P.-D INSP.: 9 TEST: 13 CODE: OS=7/69
HEADING: O.K. GR./CAL.: 308 WIN.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

EVIDENCE OF TRIGGER BURRS BINDING. TRIGGER 1.074
(MODEL DRAWING 1.076) EXCESSIVE LUBRICANT-TOO HEAVY.
TRIGGER CONNECTOR-SEAR ENGAGEMENT .015 (MIN. 15.020)

COMPLAINT: "FIRED WHEN SAFETY WAS RELEASED"

INCIDENT: FOLLOW-DOWN.

COMMENTS: THE TRIGGER BIND, HEAVY LUBRICANT COMBINATION
PROBABLY CAUSED THE FOLLOW DOWN.