



January 2, 1992

Remington Arms, Co., Inc.
14 Hoefler Avenue
Illion, New York 13357

Gentlemen:

I am the owner of a Remington Model 722, bolt action rifle. The serial number of the weapon is 170782.

Several times when the spent shell is rejected, and the bolt pushed forward to reload, it has fired for no apparent reason. Please furnish me instructions on the procedure to either have the weapon repaired or replaced.

The rifle is unsafe in its present condition, and I am reluctant to fire it.

Thank you for your immediate attention to this matter.

Sincerely,

Salvatore Varvera

Salvatore Varvera
13935 Davey
Florissant, MO. 63034

Phone (314) 9216823