

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER	
INITIAL				CUSTOMER ORDER NO.		R 94-11102	
FPS V588424860				6788133			
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE		
03/25/94	03/28/94	DY 9-74	0473		700 30-06 B&L		
ACCESSORIES							
w/ studs scope base							
FROM:				SHIP TO:			
VAN FLEET, THOMAS L. 11640 N. PEARSON RD. KELLER, TX 76248				VAN FLEET, THOMAS L. 11640 N. PEARSON RD. KELLER, TX 76248			
CUST NO 094951 G.O.B.							
ACCOUNT NUMBER		ACCOUNT NUMBER NC		FROM DATE		ESTIMATED	
063103 SC.				3/29		UPS	
GUN CONDITION		WRITE ☐				REPAIR CHARGE 15.00	
☐ NEW ☐ LIGHTLY WORN ☒ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☒ MARRED		SEND FOR B&L of Arms				EXCISE TAX INSURANCE UPS PARCEL POST TOTAL	
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE	A1	B1				discharged when safety released	
TRIGGER GROUP		B2			E1	F1	
BOLT ASSY.		B3			E2	F2	
BARREL ASSY.		B4		D1	E3	F3	
REC. ASSY.		B5		D2	E4	F4	
WOOD			C1	D3	E5	F5	
METAL			C2				
MAIN FAULT							
Upon receipt of the firearm of the gun, we could not inspect customer							
Comes. Information needed a part of only type information before the gun							
part of the gun safety gun. Action could not move. Build up of dirt and trapping							
oil trigger part - 4 1/2 the left side of the gun.							
PARTS							
300 left - .011							
26345 Trigger Assembly							
Comments							
cannot check for a LL							
Safety checks out 4 1/2 the gun							
Replace trigger gun and							
then action at 1/2 round up and							
no action of good result							
To check							
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN		
FB.							
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE		
OFFICE COPY							
RD6925 REV. 1/94							

to A/S 5/19/94