

RECEIVING AND ESTIMATING REPORT

INITIAL FPS		CUSTOMER ORDER NO.		COMMENTS L/SIGHTS	
DATE RECEIVED 12/14/90	DATE OPENED 12/19/90	DATE CODE LK 2-90	SERIAL NUMBER C6497927	MODEL AND GRADE 700 7MM-08 BDL	ORDER R 90-332
ACCESSORIES SCOPE BASE					
FROM: VICTORIA ARMY SALES 1902 HOUSTON HWY. VICTORIA TX 77901			SHIP TO: VICTORIA ARMY SALES 1902 HOUSTON HWY. VICTORIA TX 77901		
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☒	CLEAN/TEST	PROM. DATE	ESTIMATED 1-9-91
				VIA	UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

Gun fires upon opening the Bolt

MAIN FAULT

No fault found - cannot duplicate complaint - trigger and safety assembly function properly. Trigger pull 5#, rear-lift .011". Rifle cannot be made to malfunction.

PARTS

*Offer to return rifle as-is or, we
will install a new trigger assembly
at 500000 price, as a gesture of
good-will, if it will better restore
confidence in the rifle.*

REPAIRMAN V.B.L.	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6923 REV. 7/90