

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL LCS	CUSTOMER ORDER NO. 29480						
DATE RECEIVED 01/04/91	DATE OPENED 01/10/91	DATE CODE BV 1-79	SERIAL NUMBER A6698848	MODEL AND GRADE 700 270 BDL			ORDER R 91-009
ACCESSORIES W/STUDS		L/SIGHTS					

FROM:

VILLAGE SPORTS
2601 FERRAND
MONROE

LA 71201

SHIP TO:

VILLAGE SPORTS
2601 FERRAND
MONROE

LA 71201

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW☒ SLIGHTLY WORN☐ VERY WORN☐ MISUSED☐ MARRED

CUSTOMER'S REQUEST

"The trigger when pulled is not firing the rifle"

MAIN FAULT

As received, firing pin fell very slow. Inspection revealed trigger assembly and bolt stop contaminated with sticky gunning residue. Sear-safety cam sticking to side plate of trigger assembly. Trigger pull 5 1/2 #; sear lift .007".

PARTS

Clean present trigger assembly, if possible. If not, send quotation for $\frac{1}{2}$ normal cost, for replacement trigger as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/9