

RECEIVING AND ESTIMATING REPORT ✓

INITIAL PS		CUSTOMER ORDER NO. 010065325RC		COMMENTS			
DATE RECEIVED 2/18/90	DATE OPENED 12/21/90	DATE CODE OF 7-85	SERIAL NUMBER B6731184	MODEL AND GRADE 700 270 WIN ADL		ORDER R 90-33598	
ACCESSORIES W/STUDS							

FROM: WAL MART 65 HWY 66 & CUMBERLAND SULLIVAN MO 63080	SHIP TO: WAL MART 65 HWY 66 & CUMBERLAND SULLIVAN MO 63080
--	---

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
--------------	--------------------	--------------------------------	------------	------------	-----------	------------

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

safety broken - fires when pushed off

MAIN FAULT

1) Scan engagement tampered with outside of factory - no engagement as received - sealant is not Remington sealant

2) Safety lever was removed from rifle outside of factory - incorrectly replaced - Detent ball and retainer spring missing

Safety is not broken, it is now incomplete!!

RTS

Sent repair quotation for new trigger assembly.

Product Serial is retaining present assembly.

REPAIRMAN LEW	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90