

#22



CUSTOMER'S REQUEST Fire when shell ejected & Bolt is closed

MAIN FAULT

Trigger assembly nested internally from unknown source
Internal Trigger parts not moving freely

PARTS	
	Replace Trigger assembly under warranty

	REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV 6/88