

WUU-19

MARCH 28, 1983

REMINGTON ARMS Co.
BRIDGEPORT, CT 06602

I OWN A MODEL 700 BDL LH. 30-06 CALIBER.
RECENTLY I FIRED A SINGLE SHOT, CHAMBERED
A FRESH ROUND FROM THE MAGAZINE, THEN
PUT THE SAFETY IN THE "SAFE" POSITION.
A FEW MINUTES LATER I DECIDED TO RELOAD.
WHEN I FLIPPED THE SAFETY OFF, THE
GUN FIRED WITHOUT MY TOUCHING THE
TRIGGER.

SINCE THEN I HAVE TRIED TO GET THE
EMPTY GUN TO REPEAT THIS INCIDENT, BUT
HAVE BEEN UNABLE TO.

THIS WORRIES ME AND I CONSIDER IT
UNSAFE. PLEASE ADVISE WHAT COURSE
OF ACTION I SHOULD TAKE TO GET THIS
CONDITION CORRECTED.

STEVE WALKER
Rt 1 Box 199
SLATER, MO 65549

P.S. THE TRIGGER PULL HAS NOT BEEN ALTERED,