

RECEIVING AND ESTIMATING REPORT									
CUSTOMER ORDER NO.				COMMENTS					
				J STEKL					
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	270		ADL	ORDER	
05/19/88	05/31/88	PH 6-87	B6867418	700				R	88-15784
ACCESSORIES		W/STUDS		L/SIGHTS					
FROM:				SHIP TO:					
LATHMAN SERVICE CTR. RT 3 DRESDEN, TN.				LATHMAN SERVICE CTR. RT 3 DRESDEN, TN.					
				38225		38225			
ACCOUNT NUMBER				FROM DATE		ESTIMATED		VIA	
								UPS	
REPAIR CHARGE		TAX ST	INSURANCE	UPS	PARCEL POST	TOTAL			
		TAX CITY				\$			
GUN CONDITION:				☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ QUOTE					
CUSTOMER'S COMPLAINT				<i>"bolt falls down on closing" "one day it went off when I pulled it"</i>					
MAIN FAULT				<i>Trigger has been adjusted outside factory: 1) trigger pull 1 1/2 lbs. no spring retention; 2) Sear engagement has been set below Remington specification.</i>					
PARTS				<i>Re-adjust trigger assembly to Remington specifications - return to customer. Charge as required</i> <i>6/16/88</i> <i>JMB</i>					
FOR COMPUTER REF. ONLY				PROOF					
				(CLEAN) (TEST) (TARGET)					
				REPAIRMAN					