

STELL

L/REAR SIGHT

WV 26346

CUST NO: 067888 C.O.D L

WRITE

☐ NEW  
☐ LIGHTLY WORN  
☒ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE  
☐ MARR'D

*sometimes fires on closing*

IN FAULT  
Triggen assembly inspected as received — assembly is contaminated with a gummy substance that is inhibiting movement of internal trigger parts. Gear-Safety cam is affixed to trigger assembly in place. Trigger assembly has also been improperly adjusted outside factory — Gear engagement and over-travel are excessive.

COMMENTS Offer near, terms, reasonably at  
to normal cost, and gesture of  
good will.

|                |       |       |      |        |         |
|----------------|-------|-------|------|--------|---------|
| REPAIRMAN      | PROOF | CLEAN | TEST | TARGET | PATTERN |
| GALLERY TESTER | DATE  | DATE  | DATE | DATE   | DATE    |

RD6925 REV. 1/92

PPS 05341