

RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO.		COMMENTS			
LCS							
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER	
11/30/90	12/05/90	BC 1-82	B6370339	700	243 BDL	R	90-3163
ACCESSORIES		SLING STRAP W/STUDS		W/SWIVELS		SCOPE BASE	
FROM:				SHIP TO:			
WARNER, ROGER 4504 STYPES BRANCH RD SALEM VA 24153				WARNER, ROGER 4504 STYPES BRANCH RD SALEM VA 24153			
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		WRITE ☐		CLEAN/TEST	
						VIA UPS	

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

fires on bolt closing

MAIN FAULT

Trigger assembly is contaminated with heavy, gummy residue. Internal trigger parts not able to move freely. Sem-safety cam and Trigger and connector sticking to side plate of trigger assembly. Improperly maintained!

PARTS

Send quotation to clean present trigger assembly, if possible. If not send quotation for replacement assembly at 1/2 normal cost, as a gesture of good-will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
BWT					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90