

REPAIR OR REPLACEMENT ORDER

No. 20097

☒ WARSHAL'S SPORTING GOODS CO.

1000 - 1st AVE.

604-7200

Seattle, Wash. 98104

Ship to

Dec 24 1979 T5
REMINGTON ARMS CO.

ARMS SERVICE DIVISION

ILION NY 13357

Article

ONE REM 700 # ALL 96592 URGENT EXPRESS

THIS GUN INVOLVED IN ACCIDENT. CUSTOMER SAYS

FIRED ON OPENING HITTING A PICKUP TRUCK

CUSTOMER IS LA BLAUF M PARKER

15022 ST 15TH

BELLEVUE

7804

☐ REPAIR☐ REPLACE☒ Prepaid☐ Collect

VALUE: \$

330.00

Customer

STORE TAX

Address

☒ Main☐ Stock☐ Northwest☐

Tel. No.

CONSIGNED COPY

pany. Trigger pull was well within our specifications at 4 1/2 pounds.

Based on our findings, Remington Arms Company, Inc., cannot accept any liability or responsibility for the incident. We can only assume that at the instant the bolt was grasped, accidental contact was made with the trigger, causing the gun to fire.