

RECEIVING AND ESTIMATING REPORT

CUST NO: 047018 C.O.D		COMMENTS	
INITIAL JM	CUSTOMER ORDER NO.		
DATE RECEIVED 7/29/91	DATE OPENED 08/05/91	DATE CODE EU 10-71	SERIAL NUMBER 6485398
MODEL AND GRADE 700 300WIN		MAG/BDL	
ACCESSORIES W/STUDS		SCOPE BASE	
L/SIGHTS		ORDER R 91-14967	
FROM: WHIPPLE, CHARLES A 16 OLD BROOK STATION RD P O BOX 679 PRINCETON MA 01541 USA		SHIP TO: WHIPPLE, CHARLES A 16 OLD BROOK STATION RD P O BOX 679 PRINCETON MA 01541 USA	
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST
PROM. DATE		ESTIMATED 8-26-91	VIA V463597633

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☒ MARRED					

CUSTOMER'S REQUEST

Fired accidentally when I moved safety to off.

MAIN FAULT

Cannot duplicate reported incident, however, trigger assembly has been improperly adjusted out of spec - trigger pull 2.5# (below spec.) overtravel excessive. Trigger assembly contaminated with partially dried lubrication. Rifle has no top to bottom of receiver. Surprisingly maintained.

ARTS	Offer to clean and re-adjust present trigger assembly (if possible) Or, we can install a new trigger assembly at a normal cost, as a gesture of good-will.					
REPAIRMAN DE	PROOF	CLEAN	TEST	TARGET	PATTERN	
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE	

OFFICE COPY

RD6925 REV. 7/90