

BARBER - Kinzer PPS GAL RE0005537

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 93-22487

CUSTOMER ORDER NO.

BOTTOM HALF OF MOUNTS ONLY

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
19/93	10/21/93	DX 9-73	6668023		700 7MM MAG
W/STUDS		SCOPE BASE		L/SIGHTS	

SHIP TO:

WILSON, ALBERT F
RT 8 BOX 580
CROSSVILLE

TN 38555

WILSON, ALBERT F
RT 8 BOX 580
CROSSVILLE

TN 38555

CUST NO: 085783 C.O.D.

INVENTORY NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
				11/5/93	UPS
CONDITION					REPAIR CHARGE
WORK					25.00
SLIGHTLY WORN					EXCISE
DRN					TAX
SLIGHTLY WORN					INSURANCE
UNREPAIRABLE					UPS
REPAIRED	PARCEL POST				
	TOTAL				

OWNER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
E	A1	B1				
OWNER GROUP		B2	FIRED WHEN FLIPPING ON SAFE			
ASSY.		B3		E2	F2	
REL ASSY.		B4		D1	E3	F3
ASSY.		B5		D2	E4	F4
D			C1	D3	E5	F5
AL			C2			

FAULT SEND TO PRODUCT SERVICE Dept May 1993
 Unable to duplicate concern. Examination revealed heavy build up of sticky
 substance on action and trigger assembly. Safety has been removed from the
 trigger adjustment and stop adjustment screws, indicating they have been
 tampered with. Both screws have been back out.

COMMENTS

Replace complete trigger assembly &
 clean action at 1/2 normal replacement
 cost, no question of good will
 go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
122		✓	✓		
GALLERY TESTER	DATE	DATE			DATE

RD6925 REV 1/92

BARBER - Kinzer PPS GAL RE0005537

PPS 05532