

REPAIR GUN UPDATE FUNCTION: I (N)EXT (P)REV (U)PDATE (I)NQ (E)XACT 03/26/93
 ENTER REPAIR NUMBER -----> 9303819 14 14 24
 SERIAL NO: 119540 NEW SERIAL NO: MODEL: 700
 FROM: (CUST NUM: 075041) WORRALLGER GA/CAL: 30-06
 HUGHES, JOHN TYPE: ADL
 708 HIGH STREET ACCESSORIES:

POTTSTOWN PA 19464
 SHIPPED TO:
 JOHN HUGES
 208 HIGH ST
 728
 POTTSTOWN PA 19464
 COMMENTS: ATTN R POTTER

DATE CODES: DL 9-64 2ND TIME IN
 OTHER ACCESSORIES:

DATES: TO FROM
 RECEIVED 01 27 93 BATTERY 02 11 93 02 18 93 ENTERED BY: JJM
 OPENED 02 05 93 PROD SERV 00 00 00 00 00 00 REPAIRMAN: JJB
 ESTIMATED 00 00 00 TAG GUNS 00 00 TYPYST:
 PROMISED 00 00 00 REJECTED 00 00 CORRESPONDENT:
 REPAIRED 00 00 00 CASH RECEIVED:\$ 0.00 BILL TYPE: D
 SHIPPED 02 19 93
 BILL TYPE COD PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PFS=CUST MAIN

REPAIR NUMBER: 9303819 CHARGE (AWAIT RESP) COD PRINTED 03/26/93
 CUSTOMER NAME: HUGHES, JOHN 14 15 40

REQUEST: GUN ACCIDENTLY DISCHARGED - SEE LETTER
 MAIN FAULT: UNABLE TO DUPLICATE CUSTOMERS CONCERN. HOWEVER, EXAMINATION
 REVEALED THAT THE TRIGGER ASSEMBLY IS COVERED WITH STICKY
 SUBSTANCE. SEAR SAFETY CAM SLUGGISH. ACTION NEEDS GOOD
 CLEANING. TRIG PULL 4 1/2 LBS. -
 DATE OF MFG: 1964

PARTS: \$ 28.50 1 26345 TRIGGER ASSEM RH
 \$ 0.00 19900005 TEST
 \$ 0.00 19900004 CLEAN
 LABOR: \$ 0.00 POLISHED CHAMBER
 \$ 0.00 REPLACE TRIGGER ASSEMBLY AT 1/2 NORMAL REPLACEMENT COST
 \$ 0.00 AND CLEAN ACTION.
 \$ 0.00 CUSTOMER APPROVED PER PHONE 02/05/93
 \$ 0.00 CALLED 2/10/93 CHANGED SHIP TO ADDRESS
 \$ 0.00 JJB/HAR

REPAIRMAN'S INITS: JJB NUM OF WKS: 04 CORRESPONDENT'S INITS:
 TOTAL VALUE:\$ 38.21 PF1 = INQ PF2 = ESTIMATE
 NO MORE DATA AVAILABLE FOR THIS REPAIR

3/26/93 to Fun Cole
Found in Ammo Service Address wrong
re-shipping 3/29/93