

P.I. YES GUN EXAMINATION REPORT NUMBER: 152 MODEL: 700 A
 GENERAL CONDITION: SHOWS CONSIDERABLE USE R #: 25120
 OUTSIDE WORK: BARREL CUTOFF BEHIND FRONT SIGHT, SIGHTS REMOVED KNOW MISSING DATE: 10/24/79
SLING SWIVEL STUDS ADDED, BEDDING CHANGES FROM: JACKSON P.
TOP RECEIVER, PLUG SCREWS MISSING
 FIRED AMMO TYPE: NOT KNOWN STARK %OTIM YAUGER
 & CONDITION: GUN #: 124114
 PROOF: (REP) INSP.: U TEST: 15 CODE: BM = 1-65
 HEADING: CLOSES SLUG ON EXTREME MAX PLUG GA./CAL.: .222 REM.
 BREECH OPENING: OK 9-26-79 W.A. WARE, JR.
 RECOIL SHOULDERS: OK CHECKED BY: M-HARDY
 CHAMBER: OK APPROVED: SPH 11/4/79
 TEST: APPROVED: RY 11/1/79
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: C.F.B. 11-2-79
STOCK IS MARRED; WEAR MARKS ON BOLT, TRIGGER
GUARD, AND BARREL, BEDDING ALTERED IN FORE-END
WITH PAPER SHIM AND SCOTCH TAPE, MAGAZINE
BOX TAPED, SEAR AND SEAR SAFETY CAM-FIRING PIN
HEAD CONTACT SURFACES APPEAR TO BE IN GOOD CONDITION
 COMPLAINT: IT IS ALLEGED GUN FIRED AT SOME
POINT WHILE MANIPULATING BOLT DURING UNLOADING
 INCIDENT: HUNTING COMPANION WOUNDED

COMMENTS: TRIGGER PULL IS 1/2". TRIGGER ADJUSTING SCREW SEALANT HAS
BEEN REMOVED. THE TRIGGER PULL HAS BEEN ALTERED DOWN TO
APPROX 1/2". TRIGGER ADJUSTING SCREW HAS BEEN STRUCK WITH
A SHARP OBJECT. THESE ALTERATIONS WERE DONE OUTSIDE OF
FACTORY. THE TRIGGER ASSEMBLY HAS BEEN REMOVED FROM
THE RIFLE OUTSIDE OF THE FACTORY, AS EVIDENCED BY BOLT
STOP PIN REVERSAL
THE EXTREME ALTERED TRIGGER ADJUSTING SCREW SETTING
CAUSED INSUFFICIENT TRIGGER SPRING FORCE.
BY SLAMMING THE BOLT CLOSED EXCESSIVELY HARD OR FAST,
THE GUN CAN BE MADE TO FOLLOW DOWN.
SEAR ENGAGEMENT APPEARS TO BE CORRECT. THE GUN
PASSES THE TRICE TEST.
WHEN THE BOLT IS OPERATED IN A NORMAL MANNER,