

PAGE (2) of (5)

UML-14

MOD. 700R# 06332Ser No. A6647268P.I. NoRecd. 02-2-83MFD. 8-78Checked By SLC JohnsonNUMBER

6-9-83

COMMENTS:

THIS GUN WAS COCKED, ITS SAFETY WAS SWITCH TO THE "S" POSITION, AND IT WAS PLACED INSIDE A COLD BOX (INSIDE THERMOMETER INDICATED -30F) AT 4:35 P.M. ON 06 APRIL 83.

UPON REMOVAL OF THIS GUN FROM THE COLD BOX (INSIDE THERMOMETER INDICATED -29F) AT 9:40 A.M. ON 07 APRIL 83,

THE FOLLOWING TEST WAS IMMEDIATELY PERFORMED:

① Pull trigger to see if it binds or sticks back —
IT DID NEITHER!

② Switch safety to "F" position — IT DID NOT FIRE-DOWN.

③ Open bolt and check for ammo — NONE

④ Close bolt and work safety — POSITIVE, SNAPPY ACTION.

⑤ Switch safety to "S" position, pull back hard on trigger, release trigger, switch safety to "F" position. Repeat this three times. — THE FIRING PIN DID NOT FIRE-DOWN.

⑥ With safety switched to "F" position, pull trigger. — THE FIRING PIN FIRED-DOWN. THE FIRST TIME IT FIRED-DOWN

SLUGGISHLY AND SUBSEQUENT FIRE-DOWNS WERE SNAPPY.

⑦ Recock the bolt and repeat the entire test. — No

PROBLEMS ENCOUNTERED AND NO F.S.R. OBSERVED.

⑧ Perform "trick test". — GUN PASSED THE "TRICK TEST".