

Remington Arms Co., Inc.
Product Service
Legal Case #:1943

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
138690	12/28/2007	1/4/2008	1/4/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Grundmans	Grundmans		75 Wildwood Ave	Rio Dell	CA	95562		
Incident		Mark	Berry II	1134 Harris St	Eureka	CA	9550		H 707-436-8674

Incident Information - None Defined

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 WIN MA	27313	S6576868	WA	8/17/2006 11:14:33 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ACUSPORT (OH) CORPORATION		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA at n/c						
	Repair/Replacement Cost	Repair/Replacement Date				
	35.00	1/10/2008				

1/10/08-replace ta at n/c to restore confidence in rifle.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/4/2008
	Product Type		RF
	Action Type		A
	Assigned To		E.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 300 WIN MAG SS FLUTTED
	Date Code		WA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	

	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	CHIPPED AT GRIP
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 X-MARK PRO
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.009
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	3.5#
	Altered	False	NO SEALANT ON ADJUSTING SCREWS
	Sub-Assembly	X-Mark Pro	

1943

WA 8/06
26 11
3.5#
1009

Remington.

REMINGTON ARMS COMPANY, Inc. 096372

ILION, NEW YORK 13357

REMINGTON GUN REPAIR INVOICE

Dealer No.

1207

Remington Repair Facility

Name

GRUNDMANS

Street

75 WINDWOOD AVE

City

Riv Dell

State

CA

Zip

95562

Customer's Name

MARK BERRY II

Street

1134 HERMUS ST

City

EUREKA

State

CA

Zip

95562

Telephone No.

707-436-8674

Date Firearm Received

12-4-07

Date Returned to Customer

Code

WA

Barrel Code

Date Mfg. Mo. & Yr.

Date Returned to Factory

12-5-07

Gun Model

700

Cal. or Gauge

300 WIN

Grade

Serial Number

S6576868

Complete Description of Customer's Complaint

Customer claims gun fired
when safety taken off - (twice)

Repairs Performed - Describe in detail

Return to factory for their
inspection as requested for trigger
malfunctions

Serial Number: S6576868

Model: 700



RE00138690

could not duplicate
replace trigger mechanism
AT N/C to restore confidence
w. rifle. immediately

Retail Value

Repair Charge Breakdown

Parts

\$

Labor

\$

Shipping

\$

Total

\$